

Florida Boat & Yacht Surveyors

Marine Infrared Thermographic Inspection

Thermographer: Jeff Hahn

Inspection Date: May 4, 2004

Report Prepared Date: May 4, 2004

Customer Name: John Sample

Vessel Name: Sample Vessel

Vessel Area Inspected Stern under swim platform


Black and White Infrared Image




Color Infrared Image



Iso-Therm Infrared Image



Visual Photographic Image



Finding

Void in fiberglass reinforced plastic hull at the stern. Stress on the material from the swim platform appears to have contributed to the failure of this structural section of the vessel.

Recommendation

Seek advice from qualified fiberglass repair facility.